

## Correspondence by Project

Project Number:

561533337

| Correspondence Number | Memo                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
|-----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| I28-P330I-1           | <p>1) EUT is not capable of running both transmitters at the same time.</p> <p>2)Bandedge data was corrected and can be found in the test report. 3) The calculation of the limit for 9KHz-30MHz can be found in the test report. 4)A current copy of the certification contranct can be found with the uploads. 5) The FCC ID was corrected and can be found with the uploads. 6) The appointment letter was corrected and can be found with the uploads. 7)The users manual was corrected and can be found with the uploads. 8)The RFID was active during the conducted emissions test. 9) The RFID and HID was active during the temp/power variation test. 10) Confidentiality was not requested.</p> |