Response to E04-000102-1

- 1. The original testing was performed between 12/19/03 and 1/16/04. The only testing after 1/16/04 was RSS131 and the input and output plots, which have current calibration dates.
- 2. The only changes of note are to the RF output transistors which have gone from Motorola to Phillips devices and the Power Supply. The power supply was provided by Acbel for the SPA9321-30C and now is a Artesyn for the SPA9323-30C.
- 3. The MPE calculations have been removed from the test report. MPE calculations do not apply to base station equipment.
- 4. The test report has been revised to make sure the font is readable and uploaded.
- 5. Clearer block edge plots have been put in the revised test report and expanded files showing the blockedge have been uploaded.