

Tel: +886 2 26099301 *Fax:* +886 2 26099303



AUDIX Technology Corp. No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan



File Number: C1M1701334

Report Number: EM-F170107

This test report may be reproduced in full only. The document may only be updated by AUDIX Technology Corp. personnel. Any changes will be noted in the Document History section of the report.



APPENDIX C-Page 5 of 14

Tel: +886 2 26099301 *Fax:* +886 2 26099303





Figure 10 M/M: HSA-S001K, Internal View (Main Board, Back View)



File Number: C1M1701334

Report Number: EM-F170107

This test report may be reproduced in full only. The document may only be updated by AUDIX Technology Corp. personnel. Any changes will be noted in the Document History section of the report.



APPENDIX C-Page 6 of 14

Tel: +886 2 26099301 Fax: +886 2 26099303





Figure 12 M/M: HSA-S001K, Internal View (Internal Board, Back View)



File Number: C1M1701334 This test report may be reproduced in full only. The document may only be updated by AUDIX Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Report Number: EM-F170107

APPENDIX C-Page 10 of 14


Tel: +886 2 26099301 *Fax:* +886 2 26099303



AUDIX Technology Corp. No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan



Figure 20 M/M: HSA-S003K, Internal View (Battery View)



File Number: C1M1701334

Report Number: EM-F170107

This test report may be reproduced in full only. The document may only be updated by AUDIX Technology Corp. personnel. Any changes will be noted in the Document History section of the report.



APPENDIX C-Page 11 of 14

Tel: +886 2 26099301 *Fax:* +886 2 26099303





Figure 22 M/M: HSA-S003K, Internal View (Main Board, Back View)



File Number: C1M1701334

Report Number: EM-F170107

This test report may be reproduced in full only. The document may only be updated by AUDIX Technology Corp. personnel. Any changes will be noted in the Document History section of the report.



APPENDIX C-Page 12 of 14

Tel: +886 2 26099301 *Fax:* +886 2 26099303





Figure 24 M/M: HSA-S003K, Internal View (Internal Board, Back View)



File Number: C1M1701334Report Number: EM-F170107This test report may be reproduced in full only. The document may only be updated by AUDIX Technology
Corp. personnel. Any changes will be noted in the Document History section of the report.