


Test setup photographs




Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Mikrotikls SIA S/N: C65F0B82560C/002, C65F0B9B0890/002
Model: RBD53GR-5HacD2HnD-US&R11e-LTE6 IC: 7442A-D53AC
Test: 200115 FCC ID: TV7RBD53-5ACD2ND
Test to: 47CFR 15.C, 15E, RSS-247 Date: March 31, 2020
File: D53AC TSup Page 1 of 5




Rogers Labs, Inc.
 4405 W. 259th Terrace
 Louisburg, KS 66053
 Phone/Fax: (913) 837-3214
 Revision 1

Mikrotiks SIA S/N: C65F0B82560C/002, C65F0B9B0890/002
 Model: RBD53GR-5HacD2HnD-US&R11e-LTE6 IC: 7442A-D53AC
 Test: 200115 FCC ID: TV7RBD53-5ACD2ND
 Test to: 47CFR 15.C, 15E, RSS-247 Date: March 31, 2020
 File: D53AC TSup Page 2 of 5





Rogers Labs, Inc.
 4405 W. 259th Terrace
 Louisburg, KS 66053
 Phone/Fax: (913) 837-3214
 Revision 1

Mikrotiks SIA S/N: C65F0B82560C/002, C65F0B9B0890/002
 Model: RBD53GR-5HacD2HnD-US&R11e-LTE6 IC: 7442A-D53AC
 Test: 200115 FCC ID: TV7RBD53-5ACD2ND
 Test to: 47CFR 15.C, 15E, RSS-247 Date: March 31, 2020
 File: D53AC TSup Page 3 of 5



Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Mikrotiks SIA S/N: C65F0B82560C/002, C65F0B9B0890/002
Model: RBD53GR-5HacD2HnD-US&R11e-LTE6 IC: 7442A-D53AC
Test: 200115 FCC ID: TV7RBD53-5ACD2ND
Test to: 47CFR 15.C, 15E, RSS-247 Date: March 31, 2020
File: D53AC TSup Page 4 of 5



Rogers Labs, Inc.
 4405 W. 259th Terrace
 Louisburg, KS 66053
 Phone/Fax: (913) 837-3214
 Revision 1

Mikrotikls SIA S/N: C65F0B82560C/002, C65F0B9B0890/002
 Model: RBD53GR-5HacD2HnD-US&R11e-LTE6 IC: 7442A-D53AC
 Test: 200115 FCC ID: TV7RBD53-5ACD2ND
 Test to: 47CFR 15.C, 15E, RSS-247 Date: March 31, 2020
 File: D53AC TSup Page 5 of 5