



TÜV SÜD America Inc., 10040 Mesa Rim Road, San Diego, CA 92121  
Tel: (858) 678-1400. Website: [www.TUVamerica.com](http://www.TUVamerica.com)

December 31, 2018

TUV SUD BABT FCB  
Octagon House, Concorde Way  
Segensworth Rd N, Fareham  
PO15 5RL

RE: IC: 3229A-MD8800  
FCC ID: PKRNVWMD8800

We hereby attest that the above product complies with the latest version of the  
RSS-130 Issue 1 October 2013  
RSS-132 Issue 3 January 2013  
RSS-133 Issue 6 Amendment 1 January 2018  
RSS-139 Issue 3 July 2015  
RSS-199 Issue 3 December 2016  
RSS-140 Issue 1 April 2018  
RSS-192 Issue 3 January 2008  
RSS-197 Issue 1 February 2010  
FCC Part 22 Subpart H October 2018  
FCC Part 24 Subpart E October 2018  
FCC Part 27 Subpart C October 2018  
FCC Part 90 Subpart R and Z October 2018  
FCC Part 96 Subpart D October 2018



TÜV SÜD America Inc., 10040 Mesa Rim Road, San Diego, CA 92121  
Tel: (858) 678-1400. Website: [www.TUVamerica.com](http://www.TUVamerica.com)

The module was previously tested in a host under Model Number MIFI8800L. All the conducted measurements for the cell bands were from the host and covered under test report 72139211A, 72139211B, 72139211C, 72139211D, 72139211G reports.

The test results are still valid and applicable with the current requirements.

Sincerely,

A handwritten signature in blue ink, appearing to read "Xiaoying Zhang".

Xiaoying Zhang  
EMC/Wireless Test Engineer