




Fig.27




Fig.28




Fig.29




Fig.30




Fig.31




Fig.32




Fig.33




Fig.34




Fig.35




Fig.36

Test Mode: 64QAM




Fig.37




Fig.38




Fig.39




Fig.40




Fig.41




Fig.42




Fig.43




Fig.44




Fig.45




Fig.46




Fig.47




Fig.48




Fig.49




Fig.50




Fig.51




Fig.52




Fig.53




Fig.54

4 Peak-Average Ratio

Band	Carrier frequency (MHz)	Channel	BW (MHz)	RB Size	RB Offset	QPSK	16-QAM	64-QAM
4	1710.7	19957	1.4	1	5	Fig.1	Fig.2	Fig.3
4	1710.7	19957	1.4	6	0	Fig.4	Fig.5	Fig.6
4	1732.5	20175	1.4	1	5	Fig.7	Fig.8	Fig.9
4	1732.5	20175	1.4	6	0	Fig.10	Fig.11	Fig.12
4	1754.3	20393	1.4	1	5	Fig.13	Fig.14	Fig.15
4	1754.3	20393	1.4	6	0	Fig.16	Fig.17	Fig.18
4	1711.5	19965	3	1	14	Fig.19	Fig.20	Fig.21
4	1711.5	19965	3	15	0	Fig.22	Fig.23	Fig.24
4	1732.5	20175	3	1	14	Fig.25	Fig.26	Fig.27
4	1732.5	20175	3	15	0	Fig.28	Fig.29	Fig.30
4	1753.5	20385	3	1	14	Fig.31	Fig.32	Fig.33
4	1753.5	20385	3	15	0	Fig.34	Fig.35	Fig.36
4	1712.5	19975	5	1	24	Fig.37	Fig.38	Fig.39
4	1712.5	19975	5	25	0	Fig.40	Fig.41	Fig.42
4	1732.5	20175	5	1	24	Fig.43	Fig.44	Fig.45
4	1732.5	20175	5	25	0	Fig.46	Fig.47	Fig.48
4	1752.5	20375	5	1	24	Fig.49	Fig.50	Fig.51
4	1752.5	20375	5	25	0	Fig.52	Fig.53	Fig.54
4	1715	20000	10	1	49	Fig.55	Fig.56	Fig.57
4	1715	20000	10	50	0	Fig.58	Fig.59	Fig.60
4	1732.5	20175	10	1	49	Fig.61	Fig.62	Fig.63
4	1732.5	20175	10	50	0	Fig.64	Fig.65	Fig.66
4	1750	20350	10	1	49	Fig.67	Fig.68	Fig.69
4	1750	20350	10	50	0	Fig.70	Fig.71	Fig.72
4	1717.5	20025	15	1	74	Fig.73	Fig.74	Fig.75
4	1717.5	20025	15	75	0	Fig.76	Fig.77	Fig.78
4	1732.5	20175	15	1	74	Fig.79	Fig.80	Fig.81
4	1732.5	20175	15	75	0	Fig.82	Fig.83	Fig.84
4	1747.5	20325	15	1	74	Fig.85	Fig.86	Fig.87
4	1747.5	20325	15	75	0	Fig.88	Fig.89	Fig.90
4	1720	20050	20	1	99	Fig.91	Fig.92	Fig.93
4	1720	20050	20	100	0	Fig.94	Fig.95	Fig.96
4	1732.5	20175	20	1	99	Fig.97	Fig.98	Fig.99
4	1732.5	20175	20	100	0	Fig.100	Fig.101	Fig.102
4	1732.5	20175	20	1	99	Fig.103	Fig.104	Fig.105
4	1732.5	20175	20	100	0	Fig.106	Fig.107	Fig.108
4	1745	20300	20	1	99	Fig.109	Fig.110	Fig.111
4	1745	20300	20	100	0	Fig.112	Fig.113	Fig.114




Fig.1




Fig.2




Fig.3




Fig.4




Fig.5




Fig.6




Fig.7




Fig.8




Fig.9




Fig.10




Fig.11




Fig.12




Fig.13




Fig.14




Fig.15




Fig.16




Fig.17




Fig.18




Fig.19




Fig.20




Fig.21




Fig.22




Fig.23




Fig.24




Fig.25




Fig.26




Fig.27




Fig.28




Fig.29




Fig.30




Fig.31




Fig.32




Fig.33




Fig.34




Fig.35




Fig.36




Fig.37




Fig.38




Fig.39




Fig.40




Fig.41




Fig.42




Fig.43




Fig.44




Fig.45




Fig.46




Fig.47




Fig.48




Fig.49




Fig.50




Fig.51




Fig.52




Fig.53




Fig.54




Fig.55




Fig.56




Fig.57




Fig.58




Fig.59




Fig.60




Fig.61




Fig.62




Fig.63




Fig.64




Fig.65




Fig.66




Fig.67




Fig.68




Fig.69




Fig.70




Fig.71




Fig.72




Fig.73




Fig.74




Fig.75




Fig.76




Fig.77




Fig.78




Fig.79




Fig.80




Fig.81




Fig.82




Fig.83




Fig.84