ORAIMO TECHNOLOGY LIMITED Address:FLAT N 16/F BLOCK B UNIVERSAL INDUSTRIAL CENTRE 19-25 SHAN MEI STREET FOTAN NT HONGKONG Tel.: +86-0755-61803856 E-mail: dollyphin@oraimo.com

Date: 2022-07-15

FEDERAL COMMUNICATIONS COMMISSIONS Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

To whom it may concern:

The RF chip, model RTL8763EW, which installed in our product Smart Watch, Model: OSW-32N, FCC ID: 2AXYP-OSW-32N, supports BDR (GFSK), EDR (π /4-DQPSK, 8DPSK), and BLE 1M/2M functions. For use in America and this chip will not support/enable BDR (GFSK), EDR (π /4-DQPSK, 8DPSK). The BDR (GFSK), EDR (π /4-DQPSK, 8DPSK). The software.

Sincerely Yours, Signature:

Greeny. Xian

Greeny Xian Manager