


#### **SETUP PHOTOS** 11.

#### ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP





## RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)







### RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)







#### POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH USB LAPTOP





#### POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH AC ADAPTER





# **END OF REPORT**

Page 144 of 144