

Page : 1 of 4 Issued date : 2021/8/18 FCC ID : 2APLE18300421

Radiated Spurious Emission Setup Configurations

Above 1GHz







Facsimile (FAX) :+886-3-583-7948



Page : 2 of 4 Issued date : 2021/8/18 FCC ID : 2APLE18300421

30 MHz ~ 1 GHz







Telephone :+886-2-7737-3000 Facsimile (FAX) :+886-3-583-7948



: 3 of 4 Page Issued date : 2021/8/18 FCC ID : 2APLE18300421

9 kHz ~ 30 MHz






Underwriters Laboratories Taiwan Co., Ltd.
Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan Telephone :+886-2-7737-3000

Telephone :+886-2-7737-3000 Facsimile (FAX) :+886-3-583-7948



Page : 4 of 4 Issued date : 2021/8/18 FCC ID : 2APLE18300421

AC Power Line Conducted Emission Setup Configurations





Telephone Facsimile (FAX) :+886-3-583-7948