

Label Stock: Label stock must be UL listed.

Adhesive: Adhesive must be UL listed permanent adhesive

Ink: Ink must be UL listed. Color is specified by the label artwork provided.

Printer: Labels must be printed on a UL listed printer.

Artwork: Use Select Comfort supplied artwork that corresponds to the part number being printed.

Die lineDimensionsCrop marks

