



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

December 20, 2002

RE: Intel Corporation

FCC ID: PD9WM3B2100

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Please adjust the "FCC ID: XXXX" on page 4 of the OEM Notice to explain the following or similar: "where XXXXXX is replaced by the FCC on the module being integrated."
- 2) The calculations on the MPE exhibit for R (for the Ethertronics model only) are not correct. They appear to forget to take the square root. Please correct this exhibit.
- 3) The Ethertronics antenna information appears to show a higher gain in the Auxiliary column, which appears to not have been used in the test report. Please explain and/or correct the test report/MPE exhibits if necessary.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.