





832306


FCC ID: H79DC-770
Reference modification letter: No.2



FCC ID: H79DC-770

Reference modification letter: No.3,4


3



5


FCC ID: H79DC-770

Reference modification letter: No.5



FCC ID: H79DC-770


Reference modification letter: No. 8



FCC ID: H79DC-770


Reference modification letter: No.6

832306



FCC ID: H79DC-770
Front side of CRT board

832306



FCC ID: H79DC-770


Rear side of CRT board



832306

FCC ID: H79DC-770

Reference modification letter: No. 7



832306


FCC ID: H79DC-770
Mechanical construction

9


FCC ID: H79DC-770

832306

FCC ID: H79DC-770
Front side of main board





832306



FCC ID: H79DC-770

Mechanical construction



832306

FCC ID: H79DC-770

Mechanical construction