



10MHz_Middle_QPSK_50@0 -34.95dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:43:12

10MHz_High_QPSK_1@0 -34.18dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:43:32

10MHz_High_QPSK_50@0 -33.86dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:43:52

15MHz_Low_QPSK_1@0 -34.81dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:44:55

15MHz_Low_QPSK_75@0 -34.48dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:45:16

15MHz_Middle_QPSK_1@0 -34.52dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:45:36

15MHz_Middle_QPSK_75@0 -35.26dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:45:57

15MHz_High_QPSK_1@0 -34.93dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:46:19

15MHz_High_QPSK_75@0 -34.27dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:46:40

20MHz_Low_QPSK_1@0 -34.27dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:47:43

20MHz_Low_QPSK_100@0 -34.03dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:48:04

20MHz_Middle_QPSK_1@0 -34.93dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:48:25

20MHz_Middle_QPSK_100@0 -34.44dBm



ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:48:46


20MHz_High_QPSK_1@0 -34.57dBm



ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:49:07


B38 , Normal

20MHz_High_QPSK_100@0 -34.45dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:49:28

5MHz_Low_QPSK_1@0 -34.43dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:50:04

5MHz_Low_QPSK_25@0 -34.95dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:50:24

5MHz_Middle_QPSK_1@0 -34.67dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:50:44

5MHz_Middle_QPSK_25@0 -34.54dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:51:04

5MHz_High_QPSK_1@0 -34.61dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:51:23

5MHz_High_QPSK_25@0 -35.07dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:51:42

10MHz_Low_QPSK_1@0 -34.08dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:52:31

10MHz_Low_QPSK_50@0 -35.02dBm



ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:52:50


10MHz_Middle_QPSK_1@0 -34.62dBm



ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:53:09


B41_3, Normal

10MHz_Middle_QPSK_50@0 -34.72dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:53:29

3_5MHz_Low_QPSK_25@0 -34.19dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:05:49

3_5MHz_Middle_QPSK_1@0 -34.96dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:06:09

3_5MHz_Middle_QPSK_25@0 -34.48dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:06:29

3_5MHz_High_QPSK_1@0 -34.98dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:06:49

3_5MHz_High_QPSK_25@0 -34.51dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:07:10

3_10MHz_Low_QPSK_1@0 -34.28dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:07:32

3_10MHz_Low_QPSK_50@0 -33.94dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:07:52

3_10MHz_Middle_QPSK_1@0 -34.86dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:08:12

3_10MHz_Middle_QPSK_50@0 -34.17dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:08:32

3_10MHz_High_QPSK_1@0 -34.58dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:08:52

3_10MHz_High_QPSK_50@0 -34.87dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:09:11

3_15MHz_Low_QPSK_1@0 -33.86dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:09:38

3_15MHz_Low_QPSK_75@0 -34.05dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:09:58

3_15MHz_Middle_QPSK_1@0 -34.76dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:10:19

3_15MHz_Middle_QPSK_75@0 -34.28dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:10:39

3_15MHz_High_QPSK_1@0 -34.53dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:10:58

3_15MHz_High_QPSK_75@0 -34.45dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:11:18

3_20MHz_Low_QPSK_1@0 -34.34dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:11:45

3_20MHz_Low_QPSK_100@0 -34.55dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:12:05

3_20MHz_Middle_QPSK_1@0 -34.90dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:12:25

3_20MHz_Middle_QPSK_100@0 -34.40dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:12:44

3_20MHz_High_QPSK_1@0 -34.62dBm



ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:13:03

3_20MHz_High_QPSK_100@0 -35.16dBm



ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:13:23