



5200 Auto Club Dr.
Dearborn, MI 48126
(313) 593-9000

Date: April 16, 2002

Re: Certification for Lear Corporation, Receiver Model RLC-X.

Description of Changes

For the following modules:

Model	FCC ID	Canada ID
RLC-X	KOBLEAR1XR	1983 102 283A

The following changes were made:

Change capacitors C62 and C65 from 0.22 uF to 0.1 uF.

Added capacitors C60 and C70, 0.1 uF.

Added capacitor C69, 0.22 uF.

Rerouted traces and added more ground plane.