

Page: 44 of 54

### Port1\_10M\_3625MHz\_TM3.2\_CHM\_CSE0a



Port1\_10M\_3625MHz\_TM3.2\_CHM\_CSE1



Port1\_10M\_3625MHz\_TM3.2\_CHM\_CSE3




Port1\_10M\_3625MHz\_TM3.2\_CHM\_CSE0b



Port1\_10M\_3625MHz\_TM3.2\_CHM\_CSE2



Port1\_10M\_3625MHz\_TM3.2\_CHM\_CSEpart96








Page: 45 of 54

### Port1\_10M\_3695MHz\_TM3.2\_CHH\_CSE0a



Port1\_10M\_3695MHz\_TM3.2\_CHH\_CSE1




Port1\_10M\_3695MHz\_TM3.2\_CHH\_CSE3




Port1\_10M\_3695MHz\_TM3.2\_CHH\_CSE0b



Port1\_10M\_3695MHz\_TM3.2\_CHH\_CSE2



Port1\_10M\_3695MHz\_TM3.2\_CHH\_CSEpart96





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="http://www.sgs.com/en/Terms-and-Conditions.aspx">http://www.sgs.com/en/Terms-and-Conditions.aspx</a> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="http://www.sgs.com/en/Terms-and-conditions-rep-Document.aspx">http://www.sgs.com/en/Terms-and-conditions-rep-Document.aspx</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervition only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced of the company of the company



Page: 46 of 54

#### Port1\_20M\_3560MHz\_TM3.2\_CHL\_CSE0a



Port1\_20M\_3560MHz\_TM3.2\_CHL\_CSE1



Port1\_20M\_3560MHz\_TM3.2\_CHL\_CSE3




Port1\_20M\_3560MHz\_TM3.2\_CHL\_CSE0b



Port1\_20M\_3560MHz\_TM3.2\_CHL\_CSE2



Port1\_20M\_3560MHz\_TM3.2\_CHL\_CSEpart96







Page: 47 of 54

#### Port1\_20M\_3625MHz\_TM3.2\_CHM\_CSE0a



Port1\_20M\_3625MHz\_TM3.2\_CHM\_CSE1



Port1\_20M\_3625MHz\_TM3.2\_CHM\_CSE3




Port1\_20M\_3625MHz\_TM3.2\_CHM\_CSE0b



Port1\_20M\_3625MHz\_TM3.2\_CHM\_CSE2



Port1\_20M\_3625MHz\_TM3.2\_CHM\_CSEpart96







Page: 48 of 54

### Port1\_20M\_3690MHz\_TM3.2\_CHH\_CSE0a



Port1\_20M\_3690MHz\_TM3.2\_CHH\_CSE1



Port1\_20M\_3690MHz\_TM3.2\_CHH\_CSE3




Port1\_20M\_3690MHz\_TM3.2\_CHH\_CSE0b



Port1\_20M\_3690MHz\_TM3.2\_CHH\_CSE2



Port1\_20M\_3690MHz\_TM3.2\_CHH\_CSEpart96





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="http://www.sgs.com/en/Terms-and-Conditions.aspx">http://www.sgs.com/en/Terms-and-Conditions.aspx</a> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="http://www.sgs.com/en/Terms-and-conditions-rep--bocument.aspx">http://www.sgs.com/en/Terms-and-conditions-rep--bocument.aspx</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervition only and within the limits of Client's Instructions, if any. The Company's sole responsibility is to its Client and this document does not excertate parties to a transaction from exercising all their rights and obligations under the transaction document. Sind document cannot be reproduced some in the company of the co



Page: 49 of 54

### Port2\_10M\_3555MHz\_TM3.2\_CHL\_CSE0a



Port2\_10M\_3555MHz\_TM3.2\_CHL\_CSE1



Port2\_10M\_3555MHz\_TM3.2\_CHL\_CSE3




Port2\_10M\_3555MHz\_TM3.2\_CHL\_CSE0b



Port2\_10M\_3555MHz\_TM3.2\_CHL\_CSE2



Port2\_10M\_3555MHz\_TM3.2\_CHL\_CSEpart96





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="http://www.sgs.com/en/Terms-and-Conditions.aspx">http://www.sgs.com/en/Terms-and-Conditions.aspx</a> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="http://www.sgs.com/en/Terms-and-conditions-Terms-en-Document-aspx">http://www.sgs.com/en/Terms-and-conditions-Terms-en-Document-aspx</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervition only and within the limits of Client's Instructions, if any. The Company's sole responsibility is to its Client and this document does not excertate parties to a transaction from exercising all their rights and obligations under the transaction document. Sind document cannot be reproduced some in the company of the company o



Page: 50 of 54

### Port2\_10M\_3625MHz\_TM3.2\_CHM\_CSE0a



Port2\_10M\_3625MHz\_TM3.2\_CHM\_CSE1



Port2\_10M\_3625MHz\_TM3.2\_CHM\_CSE3




Port2\_10M\_3625MHz\_TM3.2\_CHM\_CSE0b



Port2\_10M\_3625MHz\_TM3.2\_CHM\_CSE2



Port2\_10M\_3625MHz\_TM3.2\_CHM\_CSEpart96







Page: 51 of 54

### Port2\_10M\_3695MHz\_TM3.2\_CHH\_CSE0a



Port2\_10M\_3695MHz\_TM3.2\_CHH\_CSE1



Port2\_10M\_3695MHz\_TM3.2\_CHH\_CSE3




Port2\_10M\_3695MHz\_TM3.2\_CHH\_CSE0b



Port2\_10M\_3695MHz\_TM3.2\_CHH\_CSE2



Port2\_10M\_3695MHz\_TM3.2\_CHH\_CSEpart96






Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic Document aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document advised that information contained hereon reflects the Company's findings at the time of its intervition only and within the limits of Client's instructions, if any. The Company's older esponsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction document. Sind document and the reproduced specific to the company's control of the company's control of the control of the company's control of the c



Page: 52 of 54

### Port2\_20M\_3560MHz\_TM3.2\_CHL\_CSE0a



Port2\_20M\_3560MHz\_TM3.2\_CHL\_CSE1



Port2\_20M\_3560MHz\_TM3.2\_CHL\_CSE3




Port2\_20M\_3560MHz\_TM3.2\_CHL\_CSE0b



Port2\_20M\_3560MHz\_TM3.2\_CHL\_CSE2



Port2\_20M\_3560MHz\_TM3.2\_CHL\_CSEpart96





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <a href="http://www.sgs.com/en/Terms-and-Conditions.aspx">http://www.sgs.com/en/Terms-and-Conditions.aspx</a> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="http://www.sgs.com/en/Terms-and-conditions-rep--bocument.aspx">http://www.sgs.com/en/Terms-and-conditions-rep--bocument.aspx</a>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervition only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. The document cannot be reproduced of the company of the company



Page: 53 of 54

### Port2\_20M\_3625MHz\_TM3.2\_CHM\_CSE0a



Port2\_20M\_3625MHz\_TM3.2\_CHM\_CSE1



Port2\_20M\_3625MHz\_TM3.2\_CHM\_CSE3



Port2\_20M\_3625MHz\_TM3.2\_CHM\_CSE0b



Port2\_20M\_3625MHz\_TM3.2\_CHM\_CSE2



Port2\_20M\_3625MHz\_TM3.2\_CHM\_CSEpart96








Page: 54 of 54

### Port2\_20M\_3690MHz\_TM3.2\_CHH\_CSE0a



Port2\_20M\_3690MHz\_TM3.2\_CHH\_CSE1



Port2\_20M\_3690MHz\_TM3.2\_CHH\_CSE3




Port2\_20M\_3690MHz\_TM3.2\_CHH\_CSE0b



Port2\_20M\_3690MHz\_TM3.2\_CHH\_CSE2



Port2\_20M\_3690MHz\_TM3.2\_CHH\_CSEpart96



### - End of the Appendix -



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Colditions/Terms-and-Po-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document advised that information contained hereon reflects the Company's findings at the time of its intervition only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction document. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing inspection report 3 certificate, please contact at telephone: (86-755) 8307 1443.