

# **INTERTEK TESTING SERVICE**

---


Report No: HK21070499

## **Configuration Photographs**

### **Worst-Case Radiated Emissions**

**(Front View)**

**Powered by Notebook USB Port + 2.4GHz Operating**



# **INTERTEK TESTING SERVICE**

---

Report No: HK21070499

## **Configuration Photographs**

### **Worst-Case Radiated Emissions**

**(Rear View)**

**Powered by Notebook USB Port + 2.4GHz Operating**



# **INTERTEK TESTING SERVICE**

---


Report No: HK21070499

## **Configuration Photographs**

### **Worst-Case Radiated Emissions**

**(Front View)**

**Powered by Notebook USB Port + 2.4GHz Operating**



# **INTERTEK TESTING SERVICE**

---


Report No: HK21070499

## **Configuration Photographs**

### **Worst-Case Radiated Emissions**

**(Rear View)**

**Powered by Notebook USB Port + 2.4GHz Operating**



# **INTERTEK TESTING SERVICE**

---


Report No: HK21070499

## **Configuration Photographs**

### **Worst-Case Radiated Emissions**

**(Front View)**

**Powered by Notebook USB Port + 2.4GHz Operating with Docking  
(Cradle)**



# INTERTEK TESTING SERVICE

---

Report No: HK21070499

## Configuration Photographs

### Worst-Case Radiated Emissions

(Rear View)

**Powered by Notebook USB Port + 2.4GHz Operating with Docking  
(Cradle)**



# INTERTEK TESTING SERVICE

---


Report No: HK21070499

## Configuration Photographs

### Worst-Case Radiated Emissions

(Front View)

Powered by Notebook USB Port + 2.4GHz Operating with Docking  
(Cradle)



# **INTERTEK TESTING SERVICE**

---

Report No: HK21070499

## **Configuration Photographs**

### **Worst-Case Radiated Emissions**

**(Rear View)**

**Powered by Notebook USB Port + 2.4GHz Operating with Docking  
(Cradle)**

