



Texas Instruments Incorporated  
12500 T.I. BLVD  
Dallas, TX 75243

December 15, 2014

FCC Laboratory  
7435 Oakland Mills Rd.  
Columbia, MD 21046

SUBJECT: FCC Application for FCC ID: Z64-WL18DBMOD

In accordance with §15.407(j), we acknowledge that should any harmful interference generated by FCC ID: Z64-WL18DBMOD to licensed services in 5.15-5.25 GHz, corrective action is required to be taken. Corrective actions may include reducing power, turning off devices, changing frequency bands, and/or further reducing power radiated in the vertical direction.

Sincerely yours,

A handwritten signature in black ink that reads 'Kelley J. Foltz'.

Contact Person: Kelley J. Foltz  
Texas Instruments, Inc.  
EPD EVM Planning Manager  
214-882-9119  
[FOLTZ@ti.com](mailto:FOLTZ@ti.com)