

Reasons for Permissive Change - 81225

No circuit or active component modifications were made on M-800-25 for this permissive change. Firmware changes to add the additional frequencies. Re-testing in report FC03-064B was necessary due to different emission masks requirements in the 821 to 824 frequency bands.