American Telecommunications Certification Body Inc.

6731 Whittier Ave, McLean, VA 22101

August 30, 2001

RE: Wacom Co., Ltd. FCC ID: HV4PL550

I am ready to issue the Grant, but I do have a couple of minor issues which need to be resolved..

- 1.) Please note that internal photos cannot be held as Confidential. This request will be ignored during the upload to the FCC website.
- 2.) Please note that loop antennas have three positions which must be addressed during low frequency testing. These are: perpendicular with the EUT, aligned along the same axis as the EUT, and parallel with the ground. The description in Section 4.2.4 of your test report is not sufficient to cover this antenna. Please confirm these three antenna orientations were tested.

Bill

William H. Graff Examining Engineer

President and Director of Engineering mailto:whgraff@AmericanTCB.com

MUMALA

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.