




Plot on Configuration VHT20 / 5300 MHz / Peak / Port 3



Date: 29.MAR.2018 12:32:17

Plot on Configuration VHT20 / 5300 MHz / Peak / Port 4


Date: 29.MAR.2018 12:36:51

Plot on Configuration VHT20 / 5320 MHz / Average / Port 1



Date: 29.MAR.2018 12:46:41

Plot on Configuration VHT20 / 5320 MHz / Average / Port 2



Date: 29.MAR.2018 12:50:53

Plot on Configuration VHT20 / 5320 MHz / Average / Port 3



Date: 29.MAR.2018 12:55:28

Plot on Configuration VHT20 / 5320 MHz / Average / Port 4



Date: 29.MAR.2018 12:59:40

Plot on Configuration VHT20 / 5320 MHz / Peak / Port 1



Date: 29.MAR.2018 12:48:43

Plot on Configuration VHT20 / 5320 MHz / Peak / Port 2



Date: 29.MAR.2018 12:52:25

Plot on Configuration VHT20 / 5320 MHz / Peak / Port 3



Date: 29.MAR.2018 12:57:12

Plot on Configuration VHT20 / 5320 MHz / Peak / Port 4



Date: 29.MAR.2018 13:00:49

Plot on Configuration VHT40 / 5270 MHz / Average / Port 1



Date: 29.MAR.2018 15:29:11

Plot on Configuration VHT40 / 5270 MHz / Average / Port 2



Date: 29.MAR.2018 15:23:07

Plot on Configuration VHT40 / 5270 MHz / Average / Port 3



Date: 29.MAR.2018 15:19:14

Plot on Configuration VHT40 / 5270 MHz / Average / Port 4



Date: 29.MAR.2018 15:14:52

Plot on Configuration VHT40 / 5270 MHz / Peak / Port 1



Date: 29.MAR.2018 15:30:35

Plot on Configuration VHT40 / 5270 MHz / Peak / Port 2




Date: 29.MAR.2018 15:26:04


Plot on Configuration VHT40 / 5270 MHz / Peak / Port 3


Date: 29.MAR.2018 15:20:56


Plot on Configuration VHT40 / 5270 MHz / Peak / Port 4


Date: 29.MAR.2018 15:16:42


Plot on Configuration VHT40 / 5310 MHz / Average / Port 1

Plot on Configuration VHT40 / 5310 MHz / Average / Port 2


Plot on Configuration VHT40 / 5310 MHz / Average / Port 3



Date: 29.MAR.2018 15:52:21

Plot on Configuration VHT40 / 5310 MHz / Average / Port 4



Date: 29.MAR.2018 17:39:02

Plot on Configuration VHT40 / 5310 MHz / Peak / Port 1



Date: 29.MAR.2018 15:40:48

Plot on Configuration VHT40 / 5310 MHz / Peak / Port 2


Date: 29.MAR.2018 15:45:52

Plot on Configuration VHT40 / 5310 MHz / Peak / Port 3



Date: 29.MAR.2018 16:52:40

Plot on Configuration VHT40 / 5310 MHz / Peak / Port 4



Date: 29.MAR.2018 18:09:19

Plot on Configuration VHT80 / 5290 MHz / Average / Port 1


Date: 29.MAR.2018 18:24:23

Plot on Configuration VHT80 / 5290 MHz / Average / Port 2



Date: 29.MAR.2018 18:27:10

Plot on Configuration VHT80 / 5290 MHz / Average / Port 3



Date 29.MAR.2018 18:30:27

Plot on Configuration VHT80 / 5290 MHz / Average / Port 4



Date 29.MAR.2018 18:34:16

Plot on Configuration VHT80 / 5290 MHz / Peak / Port 1



Date: 29.MAR.2018 18:25:40

Plot on Configuration VHT80 / 5290 MHz / Peak / Port 2



Date: 29.MAR.2018 18:28:35

Plot on Configuration VHT80 / 5290 MHz / Peak / Port 3



Date: 29.MAR.2018 18:31:17

Plot on Configuration VHT80 / 5290 MHz / Peak / Port 4



Date: 29.MAR.2018 18:35:34

Plot on Configuration VHT20 / 5500 MHz / Average / Port 1



Date: 29.MAR.2018 20:23:49

Plot on Configuration VHT20 / 5500 MHz / Average / Port 2



Date: 29.MAR.2018 20:35:01

Plot on Configuration VHT20 / 5500 MHz / Average / Port 3



Date: 29.MAR.2018 20:39:30

Plot on Configuration VHT20 / 5500 MHz / Average / Port 4



Date: 29.MAR.2018 20:42:41

Plot on Configuration VHT20 / 5500 MHz / Peak / Port 1



Date: 29.MAR.2018 20:26:04

Plot on Configuration VHT20 / 5500 MHz / Peak / Port 2



Date: 29.MAR.2018 20:37:45

Plot on Configuration VHT20 / 5500 MHz / Peak / Port 3



Date: 29.MAR.2018 20:40:46

Plot on Configuration VHT20 / 5500 MHz / Peak / Port 4



Date: 29.MAR.2018 20:43:36

Plot on Configuration VHT20 / 5580 MHz / Average / Port 1



Date: 29.MAR.2018 20:57:15

Plot on Configuration VHT20 / 5580 MHz / Average / Port 2


Date: 29.MAR.2018 21:04:06


Plot on Configuration VHT20 / 5580 MHz / Average / Port 3


Date: 29.MAR.2018 21:07:12


Plot on Configuration VHT20 / 5580 MHz / Average / Port 4


Date: 29.MAR.2018 21:10:55


C

Plot on Configuration VHT20 / 5580 MHz / Peak / Port 1



Date: 29.MAR.2018 20:58:31

Plot on Configuration VHT20 / 5580 MHz / Peak / Port 2



Date: 29.MAR.2018 21:05:09

Plot on Configuration VHT20 / 5580 MHz / Peak / Port 3



Date: 29.MAR.2018 21:08:29

Plot on Configuration VHT20 / 5580 MHz / Peak / Port 4



Date: 29.MAR.2018 21:12:20

Plot on Configuration VHT20 / 5700 MHz / Average / Port 1



Date: 29.MAR.2018 21:22:58

Plot on Configuration VHT20 / 5700 MHz / Average / Port 2



Date: 29.MAR.2018 21:25:03

Plot on Configuration VHT20 / 5700 MHz / Average / Port 3



Date: 29.MAR.2018 21:40:21

Plot on Configuration VHT20 / 5700 MHz / Average / Port 4



Date: 29.MAR.2018 21:33:25

Plot on Configuration VHT20 / 5700 MHz / Peak / Port 1



Date: 29.MAR.2018 21:45:16

Plot on Configuration VHT20 / 5700 MHz / Peak / Port 2



Date: 29.MAR.2018 21:43:05

Plot on Configuration VHT20 / 5700 MHz / Peak / Port 3



Date: 29.MAR.2018 21:42:00

Plot on Configuration VHT20 / 5700 MHz / Peak / Port 4



Date: 29.MAR.2018 21:34:44

Plot on Configuration VHT20 / 5720 MHz / Average / Port 1



Date: 29.MAR.2018 21:58:02

Plot on Configuration VHT20 / 5720 MHz / Average / Port 2




Date: 29.MAR.2018 22:03:04



Plot on Configuration VHT20 / 5720 MHz / Average / Port 3



Date: 29.MAR.2018 22:05:47

Plot on Configuration VHT20 / 5720 MHz / Average / Port 4



Date: 29.MAR.2018 22:09:36

Plot on Configuration VHT20 / 5720 MHz / Peak / Port 1

Plot on Configuration VHT20 / 5720 MHz / Peak / Port 2



Plot on Configuration VHT20 / 5720 MHz / Peak / Port 3

Plot on Configuration VHT20 / 5720 MHz / Peak / Port 4


Plot on Configuration VHT40 / 5510 MHz / Average / Port 1



Date: 29.MAR.2018 22:24:34

Plot on Configuration VHT40 / 5510 MHz / Average / Port 2



Date: 29.MAR.2018 22:27:26

Plot on Configuration VHT40 / 5510 MHz / Average / Port 3



Date: 29.MAR.2018 22:31:38

Plot on Configuration VHT40 / 5510 MHz / Average / Port 4




Date: 29.MAR.2018 22:35:04


Plot on Configuration VHT40 / 5510 MHz / Peak / Port 1


Date: 29.MAR.2018 22:25:33


Plot on Configuration VHT40 / 5510 MHz / Peak / Port 2


Date: 29.MAR.2018 22:29:07


Plot on Configuration VHT40 / 5510 MHz / Peak / Port 3

Plot on Configuration VHT40 / 5510 MHz / Peak / Port 4


Plot on Configuration VHT40 / 5550 MHz / Average / Port 1



Date: 30.MAR.2018 09:55:47

Plot on Configuration VHT40 / 5550 MHz / Average / Port 2




Date: 30.MAR.2018 10:01:22



Plot on Configuration VHT40 / 5550 MHz / Average / Port 3



Date: 30.MAR.2018 10:05:59

Plot on Configuration VHT40 / 5550 MHz / Average / Port 4



Date: 30.MAR.2018 10:09:06

Plot on Configuration VHT40 / 5550 MHz / Peak / Port 1

Plot on Configuration VHT40 / 5550 MHz / Peak / Port 2


Plot on Configuration VHT40 / 5550 MHz / Peak / Port 3

Plot on Configuration VHT40 / 5550 MHz / Peak / Port 4


Plot on Configuration VHT40 / 5670 MHz / Average / Port 1



Date: 30.MAR.2018 10:29:09

Plot on Configuration VHT40 / 5670 MHz / Average / Port 2



Date: 30.MAR.2018 10:32:24

Plot on Configuration VHT40 / 5670 MHz / Average / Port 3



Date: 30.MAR.2018 10:36:44

Plot on Configuration VHT40 / 5670 MHz / Average / Port 4




Date: 30.MAR.2018 10:40:06

Plot on Configuration VHT40 / 5670 MHz / Peak / Port 1


Date: 30.MAR.2018 10:30:20


Plot on Configuration VHT40 / 5670 MHz / Peak / Port 2


Date: 30.MAR.2018 10:33:35

Plot on Configuration VHT40 / 5670 MHz / Peak / Port 3

Plot on Configuration VHT40 / 5670 MHz / Peak / Port 4


Plot on Configuration VHT40 / 5710 MHz / Average / Port 1


Date: 30.MAR.2018 10:46:00

Plot on Configuration VHT40 / 5710 MHz / Average / Port 2



Date: 30.MAR.2018 10:49:51

Plot on Configuration VHT40 / 5710 MHz / Average / Port 3



Date: 30.MAR.2018 10:53:16

Plot on Configuration VHT40 / 5710 MHz / Average / Port 4


Date: 30.MAR.2018 10:58:04

Plot on Configuration VHT40 / 5710 MHz / Peak / Port 1


Date: 30.MAR.2018 10:47:32

Plot on Configuration VHT40 / 5710 MHz / Peak / Port 2


Date: 30.MAR.2018 10:50:56