

From: Dan Huynh [dan@ultratech-labs.com]
Sent: Monday, February 23, 2004 11:30 AM
To: tei@timcoengr.com; gretchen@timcoengr.com
Cc: Tri Luu
Subject: KEYCORP LIMITED - FCC ID: P3A-K78-205
REFERENCE: JOB 178UC4
Attn: Gretchen Torres
F. DeNuzzo

In reply to your recent question regarding the Tune Up Info:

There is no requirement for a "tune-up procedure" for the GM47 module - it is fully aligned in the factory and needs no further adjustment.

Best Regards,

Dan Huynh
Ultratech Engineering Labs Inc.