





**Equipment Photographs**

**(Internal)**



**Equipment Photographs**



**(Internal)**





**Equipment Photographs**



**(Internal)**







**Equipment Photographs**

**(Internal)**



## Equipment Photographs



(Internal)







**Equipment Photographs**

**(Internal)**



## Equipment Photographs



(Internal)





**Equipment Photographs**

**(Internal)**





**Equipment Photographs**

**(Internal)**






**Equipment Photographs**

**NFC antenna**



**(Internal)**





## Equipment Photographs

(Internal)



---

## INTERTEK TESTING SERVICE



---

Report No.: HK20101072

### Equipment Photographs

#### NFC antenna

(Internal)





Report No.: HK20101072

## Equipment Photographs

**(Internal)**

