

|                                                                                                                         |                                |          |                   |
|-------------------------------------------------------------------------------------------------------------------------|--------------------------------|----------|-------------------|
| To :                                                                                                                    | Compliance Certificate Service | From :   | I. Y. Lee         |
| Attn :                                                                                                                  | Mr. Mike Kuo                   | Ref. No. | 04-IST(Y)-0249    |
| CC:                                                                                                                     | Mr. Scott Wang                 | Date :   | November 15, 2004 |
| Tel No.                                                                                                                 | + 1 408 463 0885               | Fax No.  | + 1 408 463 0888  |
| Subject : Permissive II change application of C5F7NF0015                                                                |                                |          |                   |
| <input checked="" type="checkbox"/> Urgent <input type="checkbox"/> Confirm <input checked="" type="checkbox"/> Request |                                |          |                   |

Dear Mr. Mike Kuo

We would like to apply the permissive II change of C5F7NF0015.

The change is as follows ;

➤ Fan adding

| Model Name                                    | Model description                          | TCB Issued Date | Applied Loader | Applied Tuner |
|-----------------------------------------------|--------------------------------------------|-----------------|----------------|---------------|
| RV4000<br>SV294<br>DF-S04<br>VR2940<br>VR2945 | Basic Model                                | 06/07/2004      | BTC            | LG, Alps      |
| RV4000<br>SV294<br>DF-S04<br>VR2940<br>VR2945 | Permissive II Change<br>(Loader change)    | 09/02/2004      | LITE-ON        | LG, Alps      |
| DVR-S04<br>DF-L71N                            | Permissive II Change<br>(Front PCB change) | 09/02/2004      | BTC            | Alps          |
| DVR-S04<br>DF-L71N                            | Permissive II Change<br>(Front change)     | 10/20/2004      | LITE-ON        | Alps          |
| RV4000<br>SV294<br>DF-S04<br>VR2940<br>VR2945 | Permissive II Change<br>(Fan add)          |                 | LITE-ON<br>BTC | LG, Alps      |
| DVR-S04<br>DF-L71N                            | Permissive II Change<br>(Fan add)          |                 | LITE-ON<br>BTC | LG, Alps      |

The others, schematic, part list, user manual and operational descriptions are same with the origin.

Please find information in your web application system.

I hope your kindness.



I.Y.Lee / EMC Engineer

iylee@ist.re.kr