



HERMON LABORATORIES

December 30, 2004

American TCB
6731 Whittier Ave
Suite C110
McLean, VA 22101
Attn: Mr. Timothy Johnson, Examining Engineer

RE: your e-mail dated December 28, 2004; Airspan Networks Ltd.
FCC ID: PIDAIRSPAN-WIPLL2, ATCB001946

Dear Mr. Johnson,
Please find below the answers to your questions.

- 1) The revised list of antennas, the "aswipll_2_4GHz_ext_ant_rev1" file was uploaded on December 30, 2004 via Additional Information folder.
- 2) As mentioned above.
- 3) Please refer to Part 2 of User manual, "Safety_requirements_16078", page 2-3, where an example and details for user are given
- 4) Airspan does not supply cables for external antennas connection, so, the measurements were done without the 100 ft cable. The User Manual, part 2, page 2-3 describes the instructions for user.
- 5) By mistake the plots were mixed up. The revised test report AIRRAD_FCC.16078_rev2 with correct plots was uploaded on December 30, 2004. Please refer to plot 7.5.55 (former 7.5.49) and plot 7.5.57 (former 7.5.51).
- 6) The plots 7.5.19 – 7.5.24 (measurements with Panel antenna) and plots 7.5.58 – 7.5.63 (measurements with Omni-directional antenna) are provided in the revised test report AIRRAD_FCC.16078_rev2.

Many thanks for your assistance and patience.

Sincerely,

Marina Cherniavsky,
certification engineer
Hermon Laboratories