Thundercomm Technology Co., Ltd

Address: Building 4, No. 99, Data Valley Middle Road, Xiantao District, Yubei

District Chongqing, China Tel: +86 010-82036511 Fax: +86 010-82036511

Email: Zhouqy0710@thundersoft.com

Date: 2021-12-28

FEDERAL COMMUNICATIONS COMMISSIONS

Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046


Dear Sir/Madam,

We, Thundercomm Technology Co., Ltd hereby authorize Shenzhen Accurate Technology Co., Ltd. to act as a laboratory for testing and test report generation for the following project(s):

(Product name: Turbox-845; Model number: TurboX-C845-SOM;

FCC ID: 2AOHHTURBOXC845SOM).

We affirm that the IPEX antenna port as shown in the red box picture below, installed in our product, but for marketing purpose, two IPEX antenna port was disabled to use by manufacture in the software, the end user has no capability to activate it.



Sincerely,

Signature: Qj yong Zhou

Qiyong Zhou Manager