



Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 16.OCT.2017 23:23:28

Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 16.OCT.2017 23:27:40

Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 1 / 9GHz~18GHz




Date: 17.OCT.2017 19:41:51

Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 2 / 9GHz~18GHz




Date: 17.OCT.2017 20:03:23

Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 17.OCT.2017 19:42:41

Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 17.OCT.2017 20:04:39

Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 1 / 9GHz~18GHz




Date: 16.OCT.2017 23:44:49

Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 2 / 9GHz~18GHz




Date: 16.OCT.2017 23:52:55

Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 16.OCT.2017 23:45:07

Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 16.OCT.2017 23:52:20

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 1 / 9GHz~18GHz




Date: 17.OCT.2017 00:55:28

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 2 / 9GHz~18GHz




Date: 17.OCT.2017 01:02:22

Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 17.OCT.2017 00:55:44

Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 17.OCT.2017 01:02:00

Plot on Configuration QPSK, 80M / 5310 MHz / Average / Port 1 / 9GHz~18GHz




Date: 17.OCT.2017 01:17:19

Plot on Configuration QPSK, 80M / 5310 MHz / Average / Port 2 / 9GHz~18GHz




Date: 17.OCT.2017 01:22:55

Plot on Configuration QPSK, 80M / 5310 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 17.OCT.2017 01:17:31

Plot on Configuration QPSK, 80M / 5310 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 17.OCT.2017 01:22:19

Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 1 / 9GHz~18GHz




Date: 17.OCT.2017 20:31:02

Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 2 / 9GHz~18GHz




Date: 17.OCT.2017 20:47:04

Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 17.OCT.2017 20:31:42

Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 17.OCT.2017 20:47:56

Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 18:03:23

Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 19:28:48

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 18:02:49

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 19:29:00

Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 19:47:41

Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 19:54:08

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 19:48:01

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 19:53:44

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 20:14:38

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 20:23:26

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 20:15:19

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 20:22:37

Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 1 / 9GHz~18GHz




Date: 13.OCT.2017 01:35:33

Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 2 / 9GHz~18GHz




Date: 13.OCT.2017 01:39:08

Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 13.OCT.2017 01:35:47

Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 13.OCT.2017 01:39:27

Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 21:27:22

Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 21:35:22

Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 21:27:38

Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 21:33:47

Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 21:44:05

Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 21:49:52

Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 21:44:32

Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 21:49:26

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 21:58:02

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 22:03:35

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 12.OCT.2017 21:58:18

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 12.OCT.2017 22:02:59

Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 1 / 9GHz~18GHz




Date: 13.OCT.2017 01:36:55

Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 2 / 9GHz~18GHz




Date: 13.OCT.2017 01:38:15

Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 13.OCT.2017 01:37:15

Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 13.OCT.2017 01:37:50


Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 1 / 18GHz~40GHz



Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 2 / 18GHz~40GHz




Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 16.OCT.2017 22:20:45

Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 16.OCT.2017 22:24:26

Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 1 / 18GHz~40GHz




Date: 16.OCT.2017 23:01:49

Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 2 / 18GHz~40GHz




Date: 16.OCT.2017 23:03:03

Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 16.OCT.2017 23:00:58

Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 16.OCT.2017 23:03:29

Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 1 / 18GHz~40GHz




Date: 16.OCT.2017 23:24:56

Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 2 / 18GHz~40GHz




Date: 16.OCT.2017 23:26:31

Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 16.OCT.2017 23:24:03

Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 16.OCT.2017 23:27:00

Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 1 / 18GHz~40GHz




Date: 17.OCT.2017 19:45:49

Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 2 / 18GHz~40GHz




Date: 17.OCT.2017 20:06:32

Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 17.OCT.2017 19:47:11

Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 17.OCT.2017 20:07:25

Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 1 / 18GHz~40GHz




Date: 16.OCT.2017 23:47:13

Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 2 / 18GHz~40GHz




Date: 16.OCT.2017 23:50:50

Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 16.OCT.2017 23:46:24

Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 16.OCT.2017 23:51:13

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 1 / 18GHz~40GHz




Date: 17.OCT.2017 00:59:06

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 2 / 18GHz~40GHz




Date: 17.OCT.2017 01:00:46

Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 17.OCT.2017 00:58:26

Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 17.OCT.2017 01:01:03


Plot on Configuration QPSK, 80M / 5310 MHz / Average / Port 1 / 18GHz~40GHz



Plot on Configuration QPSK, 80M / 5310 MHz / Average / Port 2 / 18GHz~40GHz




Plot on Configuration QPSK, 80M / 5310 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 17.OCT.2017 01:18:15

Plot on Configuration QPSK, 80M / 5310 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 17.OCT.2017 01:21:33

Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 1 / 18GHz~40GHz




Date: 17.OCT.2017 20:34:32

Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 2 / 18GHz~40GHz




Date: 17.OCT.2017 20:49:36

Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 17.OCT.2017 20:35:38

Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 17.OCT.2017 20:50:23

Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 1 / 18GHz~40GHz




Date: 12.OCT.2017 18:05:13

Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 2 / 18GHz~40GHz




Date: 12.OCT.2017 19:25:53

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 12.OCT.2017 18:05:48

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 12.OCT.2017 19:11:10

Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 1 / 18GHz~40GHz




Date: 12.OCT.2017 19:49:54

Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 2 / 18GHz~40GHz




Date: 12.OCT.2017 19:51:36

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 12.OCT.2017 19:49:13

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 12.OCT.2017 19:51:55

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 1 / 18GHz~40GHz




Date: 12.OCT.2017 20:17:26

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 2 / 18GHz~40GHz




Date: 12.OCT.2017 20:20:19

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 12.OCT.2017 20:16:24

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 12.OCT.2017 20:20:49

Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 1 / 18GHz~40GHz



Date: 13.OCT.2017 01:45:57

Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 2 / 18GHz~40GHz



Date: 13.OCT.2017 01:51:15