webrobot@americantcb.com, 11:41 PM 8/24/2005 -0400, MESSAGE/ccssz/EUNLM7RG\_ATCB002677 Page 1 of 1 Hello Tim,

Please find our replies below,

1. Please find the POA updated with the proper letterhead upon your comment.

2. Please refer to the updated RF exposure exhibits uploaded upon your comment.

3. Please refer to the schematics uploaded for the TX portions upon your comment.

4. The EUT is not user-servicable for the adjusting the channel in use, all the setting is defined and set in the firmware by the manufacturer before placing in the market.

5. The device is certified under TX and DoC. Please be advised that the DoC is already tested and reported by our Taipei facilities and which is the accredited test lab for the DoC scheme.

4~5 & 7. Please find the updates on the user manual as the one uploaded by this time.

6. Please find the updates by the newly uploaded test report exhibits.

8. Okay, we will suggest the manufacturer to black-out the FCC ID on the module.

Eric 0825