


RUBICOM SYSTEMS, INC.



**FCC TEST REPORT
(INTENTIONAL RADIATOR)
FOR THE
ROCKWELL COLLINS, INC.
VHF-4000 COMMUNICATIONS TRANSCEIVER
(118-137MHz)**



Rubicom Systems, Inc.
284 West Drive, Suite B
Melbourne, FL 32904

THIS REPORT SHALL NOT BE REPRODUCED
EXCEPT IN FULL WITHOUT THE WRITTEN
APPROVAL OF THE TESTING LABORATORY

FCC TEST REPORT
(INTENTIONAL RADIATOR)
FOR THE
ROCKWELL COLLINS, INC.
VHF-4000 COMMUNICATIONS TRANSCEIVER
(118-137MHz)
S/N: FBLF

PART 5

Prepared by: _____
Joseph G. Barbee


Tested by: _____
Alex Belardinelli

Performed by:
RUBICOM SYSTEMS, INC.
284 West Drive, Suite B
Melbourne, Florida 32904


Performed for:
ROCKWELL COLLINS, INC.
1100 W. Hibiscus Blvd.
Melbourne, Florida 32901

Received: September 9, 2001

Completed: September 12, 2001



DATA SHEET 6.1-13



DATA SHEET 6.1-14

TEST: RADIATED EMISSIONS	EUT: VHF-4000	SIN: FBLF
FREQ: 200M-1GHz	SPEC: FCC PART 15	ANT. HT/POL: H
DETECTOR: QUASI PEAK AMBIENT	LINE UNDER TEST: N/A	EUT POSITION:
DATE: 9-18-01	TEST SITE: 3-METER	TESTER: AB

