

Report No.: R2207A0665

Internal photo


Configure 1:





















Internal photo Report No.: R2207A0665







































Report No.: R2207A0665


















Report No.: R2207A0665
























Item	Configure 1	Configure 2
WIFI test socket	support	remove
PL sensor	support	remove
Note: Configuration 2 only verifies the worst case		