




Tx. Spurious NVNT GFSK 5825MHz Ant1 Emission




Tx. Spurious NVNT GFSK 5745MHz Ant2 Emission




Tx. Spurious NVNT GFSK 5785MHz Ant2 Emission




Tx. Spurious NVNT GFSK 5825MHz Ant2 Emission




Tx. Spurious NVNT GFSK 5745MHz Ant1 Emission




Tx. Spurious NVNT GFSK 5785MHz Ant1 Emission




Tx. Spurious NVNT GFSK 5825MHz Ant1 Emission




Tx. Spurious NVNT GFSK 5745MHz Ant2 Emission



Tx. Spurious NVNT GFSK 5785MHz Ant2 Emission



Tx. Spurious NVNT GFSK 5825MHz Ant2 Emission




Appendix B: photographs of test setup

Conducted emissions at AC power line (150kHz-30MHz)



Radiated Emissions (30MHz-1GHz)



Radiated Emissions (above 1GHz)



Appendix C: photographs of EUT

Reference to the test report no. BLA-EMC-202502-A3801

----END OF REPORT----

The test report is effective only with both signature and specialized stamp, the result(s) shown in this report refer only to the sample(s) tested. Without written approval of BlueAsia, this report can't be reproduced except in full.

BlueAsia