



Description of the differences between the new board and the original board



Reason for change: slight adjustment by the customer with sound and switch to charging IC CL4054H with OVP protection:

序号 /NO		name	Q37S-6965E (old)	Q37-WRM (new)
1		Silkscreen name/name	Q37S-6965E	Q37-WRM
2	U2	power amplification IC	CS5250	LTK5313
3	R33	Resistor	2.2K	470R
4	R28	Resistor	8.2K	NC
5	U10	charge IC	MX4054	CL4054H
6	C8	capacitor	68NF	47NF
7	R5 C7	Resistor & capacitor	20K , 68NF	NC
8	C15	capacitor	470UF (VT)	470UF (VT / CS /CK) general
9	R18	Resistor	NC	0R
	C4	capacitor	150K	10UF

Sincerely,

<Signature>

Name: Roy Ryan



Title: manager

Company: DP Audio Video LLC