US Tech Test Report:
 FCC Part 15 Certification

 FCC ID:
 07P-RL78

 IC:
 10147A-RL78

 Test Report Number:
 17-0165

 Issue Date:
 November 2, 2017

 Customer:
 Inventek

 Model:
 ISMRL78G1D

INTERNAL PHOTOGRAPHS



Figure 1. Component Side of BLE Module, Shielding Removed

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification O7P-RL78 10147A-RL78 17-0165 November 2, 2017 Inventek ISMRL78G1D



Figure 2. Solder Side of BLE Module