


Label Location



Part No :

Model : ADB10HSAN

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-ADB10HSAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation Is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : ADB30HSAN

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-ADB10HSAN

프린팅 영역(33X10)

Contains FCC ID : YZP-VL3000

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation Is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : ADB10HSGG

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-ADB10HSAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation Is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : ADB11HSGG

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-ADB10HSAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation Is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : ADB10HSGN

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-ADB10HSAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation Is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : ADB10HSGL

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-ADB10HSAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation Is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : DA350HSGG

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-ADB10HSAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation Is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : ADB10HSMG

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-ADB10HSAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation Is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : ADB10HSEG

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-ADB10HSAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : ADB20HSFN

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-ADB10HSAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : ADB10HSEP

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-ADB10HSAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : ADB11HSEP

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-ADB10HSAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : ADBC0HSEP

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-ADB10HSAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation Is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : DA350HSEP

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-ADB10HSAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation Is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : ADB10HSUG

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-ADB10HSAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation Is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : ADB10HSRP

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-ADB10HSAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation Is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd