

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1



Photo 2

UL Japan, Inc.

Kashima EMC Lab.

1614, Mushihata, Katori-shi, Chiba-ken, 289-0341 Japan

Telephone : +81 478 88 6500

Facsimile : +81 478 82 3373

Radiated Spurious Emission



Photo 1




Photo 2

Radiated Spurious Emission




Photo 1






Photo 2

Worst Case Position


X-axis



Y-axis



Z-axis



There are no electronic parts and patterns on the Receive board behind the wireless module.

Antenna Terminal Conducted Tests



Photo 1




Photo 2

End of Report

UL Japan, Inc.

Kashima EMC Lab.

1614, Mushihata, Katori-shi, Chiba-ken, 289-0341 Japan

Telephone : +81 478 88 6500

Facsimile : +81 478 82 3373