

Shenyang Sanfeng Intelligent Technology Co., Ltd

May. 08, 2023

Subject: Tuning and Adjustment of Signal booster, FCC ID: 2A34B-SFZN005

There are no external tuning adjustments, the amplifier is factory set not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Yours sincerely,

Shirley Xiong

Signature: *Shirley Xiong*