

Hyundai Corporation

Address: 140-2, Kye-dong, Chongro-ku, Seoul, South Korea.

Tel: 82-2-746-1395

Fax: 82-2-746-1051

Attestation Letter

2015-06-05

To:

Bay Area Compliance Laboratories Corp.

1274 Anvilwood Avenue

Sunnyvale, CA 94089

Dear Sir or Madam:

The RF chip, model: MT6276A which installed in FCC ID: RQQHLT-W215 supports GSM, GPRS functions. For use in the US this chip will not support/enable the HSDPA and HSUPA function. The HSDPA and HSUPA function has been shielded by the manufacturer using the software.

Best Regards,

Sincerely,

Signature:



Kyunghee Kim

Sales assistant