

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2AKFQ10032
22165-10032
22-0291
October 27, 2022
Cognosos, Inc.
PCB-10032

EXTERNAL PHOTOGRAPHS



Figure 1. Front of HOST device RT-270, RB-270

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2AKFQ10032
22165-10032
22-0291
October 27, 2022
Cognosos, Inc.
PCB-10032



Figure 2. Back of HOST device RT-270, RB-270

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2AKFQ10032
22165-10032
22-0291
October 27, 2022
Cognosos, Inc.
PCB-10032



Figure 3. Side 1 of HOST device RT-270, RB-270

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2AKFQ10032
22165-10032
22-0291
October 27, 2022
Cognosos, Inc.
PCB-10032



Figure 4. Side 2 of HOST device RT-270, RB-270

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2AKFQ10032
22165-10032
22-0291
October 27, 2022
Cognosos, Inc.
PCB-10032



Figure 5. Top of HOST device RT-270, RB-270

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2AKFQ10032
22165-10032
22-0291
October 27, 2022
Cognosos, Inc.
PCB-10032



Figure 6. Bottom of HOST device RT-270, RB-270

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2AKFQ10032
22165-10032
22-0291
October 27, 2022
Cognosos, Inc.
PCB-10032




Figure 7. Radio Module External Top View

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/IC RSS Certification
2AKFQ10032
22165-10032
22-0291
October 27, 2022
Cognosos, Inc.
PCB-10032




Figure 8. Radio Module External Bottom View