

RAYMARINE LTD.

EMC Department


Test of: Raymarine Ltd.
Pathfinder RL72RC PLUS
FCC Part 80:1998
and FCC Part 2: 1998

TEST REPORT

No. 555/1000

Page 60 of 80

Issue Date: 29-10-2002



Graph PP/555/1000/01

RAYMARINE LTD.

EMC Department


Test of: Raymarine Ltd.
Pathfinder RL72RC PLUS
FCC Part 80:1998
and FCC Part 2: 1998

TEST REPORT

No. 555/1000

Page 61 of 80

Issue Date: 29-10-2002



Graph PP/555/1000/02

RAYMARINE LTD.

EMC Department


Test of: Raymarine Ltd.
Pathfinder RL72RC PLUS
FCC Part 80:1998
and FCC Part 2: 1998

TEST REPORT

No. 555/1000

Page 62 of 80

Issue Date: 29-10-2002



Graph PP/555/1000/03

RAYMARINE LTD.

EMC Department


Test of: Raymarine Ltd.
Pathfinder RL72RC PLUS
FCC Part 80:1998
and FCC Part 2: 1998

TEST REPORT

No. 555/1000

Page 63 of 80

Issue Date: 29-10-2002



Graph PP/555/1000/04

RAYMARINE LTD.

EMC Department


Test of: Raymarine Ltd.
Pathfinder RL72RC PLUS
FCC Part 80:1998
and FCC Part 2: 1998

TEST REPORT

No. 555/1000

Page 64 of 80

Issue Date: 29-10-2002



Graph PP/555/1000/05

RAYMARINE LTD.

EMC Department


Test of: Raymarine Ltd.
Pathfinder RL72RC PLUS
FCC Part 80:1998
and FCC Part 2: 1998

TEST REPORT

No. 555/1000

Page 65 of 80

Issue Date: 29-10-2002



Graph PP/555/1000/06

RAYMARINE LTD.

EMC Department


Test of: Raymarine Ltd.
Pathfinder RL72RC PLUS
FCC Part 80:1998
and FCC Part 2: 1998

TEST REPORT

No. 555/1000

Page 66 of 80

Issue Date: 29-10-2002



Graph PP/555/1000/07

RAYMARINE LTD.

EMC Department


Test of: Raymarine Ltd.
Pathfinder RL72RC PLUS
FCC Part 80:1998
and FCC Part 2: 1998

TEST REPORT

No. 555/1000

Page 67 of 80

Issue Date: 29-10-2002



Graph PP/555/1000/08

RAYMARINE LTD.

EMC Department


Test of: Raymarine Ltd.
Pathfinder RL72RC PLUS
FCC Part 80:1998
and FCC Part 2: 1998

TEST REPORT


No. 555/1000

Page 68 of 80

Issue Date: 29-10-2002



Graph PRF/555/1000/01



Graph PRF/555/1000/02

RAYMARINE LTD.

EMC Department



Test of: Raymarine Ltd.
Pathfinder RL72RC PLUS
FCC Part 80:1998
and FCC Part 2: 1998

TEST REPORT

No. 555/1000

Page 69 of 80

Issue Date: 29-10-2002



RAYMARINE LTD.

EMC Department



Test of: Raymarine Ltd.
Pathfinder RL72RC PLUS
FCC Part 80:1998
and FCC Part 2: 1998

TEST REPORT

No. 555/1000

Page 70 of 80

Issue Date: 29-10-2002



RAYMARINE LTD.

EMC Department

Test of: Raymarine Ltd.
Pathfinder RL72RC PLUS
FCC Part 80:1998
and FCC Part 2: 1998


TEST REPORT

No. 555/1000


Page 71 of 80

Issue Date: 29-10-2002

hp running



hp running



RAYMARINE LTD.

EMC Department

Test of: Raymarine Ltd.
Pathfinder RL72RC PLUS
FCC Part 80:1998
and FCC Part 2: 1998


TEST REPORT

No. 555/1000

Page 72 of 80


Issue Date: 29-10-2002

hp running



Graph PRF/555/1000/09

hp running



Graph PRF/555/1000/10

RAYMARINE LTD.

EMC Department

Test of: Raymarine Ltd.
Pathfinder RL72RC PLUS
FCC Part 80:1998
and FCC Part 2: 1998


TEST REPORT

No. 555/1000

Page 73 of 80

Issue Date: 29-10-2002

p running



hp running

