## 

To reduce the risk associated with fire due to insertion of non-authorized items into chute:

 Install security procedures and equipment appropriate to conditions; comply with applicable building codes and insurance concerns.

To reduce the risk associated with hazardous voltage due to a user attempting to service a component, incorrect installation of system components, or use of the system when damage has occurred:

- Do not attempt to modify or repair—no user serviceable parts—contact 3M Service for repair.
- Use approved system components installed by 3M Service personnel only.
- Do not use the SelfCheck system if enclosures or power cords are damaged—contact 3M Service for repair.

## A CAUTION


To reduce the risk associated with environmental contamination due to the incorrect disposal of the lithium battery in the computer, mercury in the monitor/display, or any circuitry that contains lead in the solder:


 At the end of service life, dispose of the computer, display, and other components in accordance with federal, state, and local requirements.

To reduce the risk associated with repetitive strain injury from repeated lifting of library materials:

Operation of this product may involve repeated body movements. To minimize possibility
of repetitive stress injury, avoid prolonged repetitive movements, rest when becoming
fatigued, and, when possible, alternate job functions with other people. Avoid awkward
reaching for items.

## Label locations





877\_UG\_00