

APPENDIX 3: Photographs of test setup

Radiated Emission




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Worst Case Position


LF Antenna (Type 1)

Below 30MHz: X-axis

Above 30MHz

Horizontal: X-axis / Vertical: X-axis


X-axis



Y-axis



Z-axis




LF Antenna (Type 2-2)

Below 30MHz: X-axis


Above 30MHz

Horizontal: X-axis / Vertical: X-axis

X-axis



Y-axis



Z-axis



Worst Case Position

LF Antenna (Type 3)

Below 30MHz: X-axis


Above 30MHz

Horizontal: X-axis / Vertical: X-axis


X-axis



Y-axis



Z-axis



LF Antenna (Type B)

Below 30MHz: X-axis


Above 30MHz

Horizontal: X-axis / Vertical: X-axis


X-axis



Y-axis



Z-axis



Worst Case Position


ECU

Below 30MHz: X-axis


Above 30MHz

Horizontal: X-axis / Vertical: X-axis


X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124