

Hatch Baby, Inc.

Address: 3525 Alameda De Las Pulgas, Suite D, Menlo Park, California, 94025 United States

Tel: +1 650-485-1911

Fax: +1 650-485-1911

Email: support@hatchbaby.com

Date: 2024-11-01

FEDERAL COMMUNICATIONS COMMISSIONS

Authorization and Evaluation Division

7435 Oakland Mills Road

Columbia, MD 21046

Attestation letter

Dear Sir or Madam,

Our product **Hatch Restore 3**, model: **RESTORE05**, **FCC ID: 2AFYZ-RESTORE05**, for marketing purpose, this product only supports **BT(GFSK, $\pi/4$ -DQPSK, 8DPSK), BLE1M(GFSK) and 2.4G WIFI(2412-2462(802.11 b,g,n-HT20) 2422-2452MHz(802.11n-HT40))**. The other functions, bands and modes was disabled to use by manufacturer in the software, the end user has no capability to activate it.

Meanwhile, the ESP32-WROVER-E Module(location in U7) was disabled to use the wireless function by manufacturer in the software, the end user has no capability to activate it.

Sincerely,

Signature:



Ann Crady Weiss

Title: Co-founder& CEO