


## Appendix C. Set up Photograph

## Spurious Radiation Model 1 and 2



FRONT VIEW

**REAR VIEW** 




SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C2
Report Issued Date : Jun. 20, 2006
Report Version : Rev.01

Report No. : FG640711-03

## Spurious Radiation Model 3 and 4



FRONT VIEW



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C2
Report Issued Date : Jun. 20, 2006
Report Version : Rev.01

Report No. : FG640711-03