
FCC TEST REPORT Report No.: F380603

## 1.1. Photographs of Conducted Emission Test Configuration

■ The photographs show the configuration that generates the maximum emission.



**FRONT VIEW** 



**REAR VIEW** 

**SPORTON International Inc.** TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : GX5-CW2200
Page No. : 1 of 3
Issued Date : Aug. 26, 2003

FCC TEST REPORT Report No.: F380603



SIDE VIEW

 SPORTON International Inc.
 FCC ID
 : GX5-CW2200

 TEL: 886-2-2696-2468
 Page No.
 : 2 of 3

FAX: 886-2-2696-2255 Issued Date: Aug. 26, 2003


FCC TEST REPORT Report No.: F380603

## 1.2. Photographs of Radiated Emission Test Configuration

■ The photographs show the configuration that generates the maximum emission.



**FRONT VIEW** 



**REAR VIEW** 

**SPORTON International Inc.** TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

FCC ID : GX5-CW2200
Page No. : 3 of 3
Issued Date : Aug. 26, 2003