

Non-Conformities FCC ID: MI7-IPM800 (Ref # E06-000152-1)

The items listed below represent requests for information following review of this application. Further question may arise pending review of responses to these items.

OK	#	Non-Conformity or Comment	Submitted Response	Respondent / Date of Response
X	1	Please explain the bandwidth change from 20kHz to 10kHz necessary bandwidth.	Oversight. Please use 20kHz. Provided calculated justification.	6/14/06 CKC LABS
X	2	Why was antenna port conducted data only provided in graphical form for 1-30MHz only? Typically graphical data is provided for the entire frequency range.	Plot removed; updated test report provided.	6/13/06 CKC LABS
X	3	Frequency stability testing reported in Hz, when standard is in ppm. Please report in appropriate units.	Should be 2.8892 ppm, updated test report provided.	6/13/06 CKC LABS
X	4	The provided users manual does not include any installation instructions or user cautions regarding antenna installation. Please provide updated information on antenna separation for RF Exposure.	Updated users manual provided.	6/13/06 CKC LABS
X	5	Test report references RSS 119, does application wish to pursue IC Certification also?	Not at this time.	6/13/06 CKC LABS