

主题: Response to Inquiry to FCC (Tracking Number 585246)

日期: 2018年10月12日 星期五 中国标准时间 下午9:29:57

从: oetech@fcc.gov

至: robinwu@mrt-cert.com

Inquiry on 10/09/2018 :

Inquiry:

Dear Sir,

Wireless AP added mesh mode by updating software. All hardware and RF parameters remain unchanged.

So we updated DFS report and added mesh test mode. Do we need to DFS testing in the FCC laboratory?

The FCC IDs are 2AD8UFZCWO4A1 and 2AD8UFZCWI4A1.

Looking forward to your reply.

FCC response on 10/12/2018

Hello,

The devices still need to verify DFS functionality at a test lab but it will not require FCC verification testing. The PAG can be approved through expedited review.

Attachment Details:

Do not reply to this message. Please select the [Reply to an Inquiry Response](#) link from the OET Inquiry System to add any additional information pertaining to this inquiry.