



TÜV Product Service Ltd  
Segensworth Road  
Fareham, Hampshire  
PO15 5RH  
United Kingdom  
Telephone: +44 (0)1329 443300

Ref: WS611533 – 001 Issue 1.01

4<sup>th</sup> August 2004

Direct Dial: +44 (0)1329 44479  
Fax: +44 (0)1329 443500  
E-mail: [amiller@tuvps.co.uk](mailto:amiller@tuvps.co.uk)  
Website: [www.tuvps.co.uk](http://www.tuvps.co.uk)

Mr H G Carr  
BABT  
Claremont House  
34 Moseley Road  
Walton on Thames  
Surrey  
KT12 4RQ

Dear Hilton

**TCB audit review BABT project US000057**

Following the review carried out on H9PMC9060B please find below the concerns raised during the audit and our responses: –

- 'A statement that the supplied holster contained some metal parts.'

The belt clip of the Mobile Computer Holster contains a metal spring enclosed within a plastic housing, with nominal dimensions: Overall length 80mm (formed into a semi-closed U shape); width 25mm and thickness 0.5mm.

- 'A Statement that the 'worst configuration' (which was used for test) was taken side on at 1cm separation which was closer than the holster would permit.'

For RLAN SAR assessment the MC9060 was placed against the phantom RLAN antenna side-on. This position was chosen as it represented the worst-case position for SAR measurement, the 1.0 cm separation was required in order to conform to the limits applied. It is acknowledged that this is not representative of the normal worn position of use, but considered to give the manufacturer the worst-case SAR level.

Yours sincerely

Approved By

A. Miller  
Principal Engineer

M. J Hardy  
UKAS Signatory

