

03/18/2019

TUV SUD BABT FCB
Octagon House,
Segensworth Road,
Fareham,
Hampshire,
PO15 5RL

Subject: Family Certification Request (for FCC ID: 2ASNP-E79X3562018, IC: 24793-E79X3562018)

Dear Sir or Madam,

We, dormakaba USA Inc, hereby request a family certification for FCC ID: 2ASNP-E79X3562018, IC: 24793-E79X3562018

There are no differences between the 3 HVIN's, in terms of TX frequency, reader module, hardware components, or RFID antenna. The only difference is the software configuration of the RFID reader module to set the type of credential and security scheme for the RFID cards supported by each model.

<u>HVIN</u>	<u>RFID Configuration</u>
E-PLEX E79N3	HID iCLASS Seos
E-PLEX E79N5	HID iCLASS Elite
E-PLEX E79N6	HID iCLASS (Standard)

Sincerely,



Ben Redmon
Electrical Engineer

dormakaba USA Inc.
749 West Short Street
Lexington, KY 40508
T: 859-977-3504