



Federal Communication Commission  
Authorization and Evaluation Division  
1435 Oakland Mills Road  
Columbia, MD 21046

Regarding FCC ID label placement for this application, Digital Ally, Inc. wishes to place the label inside the service door compartment due to size, aesthetics, and durability. This location will offer the end user ability to view the label before operation. The identifier label will be readily viewable when the door and cable are removed during installation. The equipment is sold and required to be mounted before operation thus exposing the label before operation.

Thank you,

Craig Staley  
Hardware Engineering Manager  
Digital Ally, Inc.

