

Circuit description

First, turn the power switch, power supply lights powered. The remote controller blade switch K1 or K2 trigger, the [SCM] MCU by internal shocks after the transmission of a high clock frequency for the first stage of shock, while single chip MCU second feet output signal for second level encoding signal amplifier. The amplified signal is transmitted to the corresponding frequency of the robot receiver.