




360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>


## 20 INTERNAL PHOTOGRAPHS



10 and 100 pF caps




360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>



top of LCD PCB



360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>



Bottom of LCD PCB






360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>




LCD PCB in top of case.



360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>




bottom of main PCB



Bottom of PCB with shields removed



360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>



Inside bottom of case with main PCB






360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>




top of main PCB in case



360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>



top PCB with shields removed








360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>




360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>







360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>





360 Herndon Parkway  
Suite 1400  
Herndon, VA 20170  
<http://www.rheintech.com>

